ATTACHMENT C 30-DAY FOLLOW-UP NOTIFICATION REPORT FORM CONTRA COSTA HEALTH SERVICES

INSTRUCTIONS: A hardcopy and an electronic copy of this report is to be submitted for all Level 2 and 3 incidents or when requested by CCHS. See Attachment C-1 for suggestions regarding the type of information to be included in the report. Attach additional sheets as necessary. This form is to be used for update reports after the initial 30-day report has been submitted. Forward the completed form to:

ATTENTION: Randall L. Sawyer Hazardous Materials Programs Director Contra Costa Health Services 4585 Pacheco Boulevard, Suite 100 Martinez, CA 94553

INCIDENT DATE:8/14/12	
INCIDENT TIME :12:16	
FACILITY:Shell Martinez Refinery	
PERSON TO CONTACT FOR ADDITIONAL IN	FORMATION
Mary Kay NyeP	hone number925-313-3358
PROVIDE ANY ADDITIONAL INFORMATION 1	THAT WAS NOT INCLUDED IN THE 72-HOUR
REPORT WHEN THE 72-HOUR REPORT WAS	S SUBMITTED, INCLUDING MATERIAL
RELEASED AND ESTIMATED OR KNOWN QUETC.:	IANTITIES, COMMUNITY IMPACT, INJURIES,
I. INCIDENT INVESTIGATION RESULTS Is the investigation of the incident complete at the lf the answer is no, when do you expect complete.	
If the answer is yes, complete the following:	
SUMMARIZE INVESTIGATION RESULTS BEL	OW OR ATTACH COPY OF REPORT:
See attached Investigation report.	

SUMMARIZE PREVENTATIVE MEASURES TO BE TAKEN TO PREVENT RECURRENCE INCLUDING MILESTONE AND COMPLETION DATES FOR IMPLEMENTATION:

Recommendation	Responsible Manager or Individual	Estimated Completion
1. For SJV-197, install a new soft goods kit including a main seat with increased H2S resistance during the August 2012 Flexicoker Turnaround	Operations Central Pressure Equipment Engineer	November 1, 2012
2. Review chemical resistance of soft goods for all PSVs relieving to the atmosphere. Verify that the chemical resistance of the soft goods are optimal for the service.	Pressure Equipment Integrity Department Manager	June 30, 2013

30-DAY REPORT, P.	AGE 2	
INCIDENT DATE:	8/13/12	
FACILITY:Shell	II Martinez Refinery	
STATE AND DESCR	RIBE THE ROOT-CAUSE(S)	OF THE INCIDENT:

The root cause of the leak was the deterioration of the viton main seat in SVJ-197. The deterioration was probably caused by the presence of H2S in the debutanizer overhead stream, which, over time caused a breakdown in the viton seat.

For CCHS Use Only:	
Received By:	
Date Received:	
Incident Number:	
Copied To:	
Event Classification Level:	