RECEIVED

72-HOUR REPORT, PAGE 2 INCIDENT DATE: <u>06/07/2023</u>

FACILITY: Martinez Refining Company LLC

JUN 1 0 2023

Contra Costa Health Hazardous Materials

72 HOUR FOLLOW-UP NOTIFICATION REPORT FORM CONTRA COSTA HEALTH SERVICES HAZARDOUS MATERIALS PROGRAMS

INSTRUCTIONS: A hardcopy and an electronic copy of this report is to be submitted for all Public Health Advisory – Level 2 and Public Protective Actions Required – Level 3 incidents or when requested by CCHSHMP. See Attachment B-1 for suggestions regarding the type of information to be included in the report. Attach additional sheets as necessary. Forward the completed form to:

For CCHSHMP Use Only:					
Received By:					
Date Received:	6/10/23				
	23060701				
Copied To:					
Event Classification	n Level: 1				

ATTENTION:

Hazardous Materials Programs Director Contra Costa Health Services Hazardous Materials Programs 4585 Pacheco Boulevard, Suite 100 Martinez, CA 94553

INCIDENT DATE:

06/07/2023

INCIDENT TIME:

1318

FACILITY:

Martinez Refining Company LLC

PERSON TO CONTACT FOR ADDITIONAL INFORMATION

Michael Marlowe Phone number (831) 332-2820

I. SUMMARY OF EVENT:

A partially treated process water leak was discovered from a pipe rack to the Effluent Treatment Plant (ETP) that flowed over a refinery parking area and into a water retention area adjacent to the refinery's property.

II. AGENCIES NOTIFIED, INCLUDING TIME OF NOTIFICATION:

Time and phone numbers to be updated in 30 day final report.

- Contra Costa Office of Emergency Services
- National Response Center
- USCG Sector SF
- OSPR
- California Regional Water Quality Control Board
- CHF
- Contra Costa Sheriff's Office

III. AGENCIES RESPONDING, INCLUDING CONTACT NAMES AND PHONE NUMBERS: CCHSD

72-HOUR REPORT, PAGE 2

INCIDENT DATE: <u>06/07/2023</u>

FACILITY: Martinez Refining Company LLC

IV. EMERGENCY RESPONSE ACTIONS:

Refinery personnel isolated the leak, contained the material and removed water from the retention area adjacent to the refinery's property. Once material was collected, cleanup of the impacted refinery parking area was conducted and pipe repairs were initiated.

V. IDENTITY OF MATERIAL RELEASED AND ESTIMATED OR KNOWN QUANTITIES:

Partially treated process wastewater.

VII.

VIII.

IX.

X.

XI.

NA

VI. METEOROLOGICAL CONDITIONS AT TIME OF EVENT including wind speed, direction, and

VERSTON NAME:	ą	REPARED BY:	Λ.	(45) 1033: 06/07/2023 15:38:12 PDT UTC-7			
06/07/2023 15:38:12		Sean Johnson	O				
	Display Nauti	ical Data					
Data from weather station	martinez station	id: MID_E7741 locate	d at 38.00883 -122.1	1833			
As of Date/Time:	06/07/2023 15:	Ė	: •				
Temperature:	68 Fahre	•	Feels Like:	68	Fahrenh	eit	
Wind Speed:	4 mph	•	Dew Point:	54	Fahrenh	neit	
Wind Direction (from):	W	•	Pressure:	29.98	in	•	
Visibility:	mile(s)	•	UV Index:				
Humidity (%):	61		Sunrise:	05:45	,	©	
Short Description:	Mostly Sunny	•	Sunset:	20:28	1	(
Full Nocreintion	Mostly Sunny	_					
DESCRIPTION OF IT None COMMUNITY IMPA		number of off-site	e complaints, air s	amplir	ng data	during event, etc.:	
Response activities co	onducted adja	acent to Marina	Vista Blvd durin	g resp	onse.		
INCIDENT INVESTI	GATION RE	ESULTS					
Is the investigation of the If the answer is no, sub-				<u>X</u>		No	
If the answer is yes, con	mplete the foll	lowing:					
SUMMARIZE INVES	STIGATION	RESULTS BELO	OW OR ATTAC	H CO	PY OF	REPORT:	

SUMMARIZE PREVENTATIVE MEASURES TO BE TAKEN TO PREVENT RECURRENCE

INCLUDING MILESTONE AND COMPLETION DATES FOR IMPLEMENTATION: