## RECEIVED

JUN 29 2023

ATTACHMENT C

Contra Costa Health Hazardous Materials

30-DAY FOLLOW-UP NOTIFICATION REPORT FORM CONTRA COSTA HEALTH SERVICES HAZARDOUS MATERIALS PROGRAMS

INSTRUCTIONS: A hardcopy and an electronic copy of this report is to be submitted for all Public Health Advisory - Level 2 and Public Protective Actions Required - Level 3 incidents or when requested by CCHSHMP. See Attachment C-1 for suggestions regarding the type of information to be included in the report. Attach additional sheets as necessary. This form is also

For CCHSHMP Use Only:

Received By:

Date Received: 6/29/23

Incident Number: 230323-01

Copied To:

Event Classification Level: 1

to be used for update reports after the initial 30-day report has been submitted. Forward the completed form to:

## ATTENTION:

Hazardous Materials Programs Director Contra Costa Health Services Hazardous Materials Programs 4585 Pacheco Boulevard, Suite 100 Martinez, CA 94553

INCIDENT DATE: <u>3/23/2023</u> INCIDENT TIME: <u>11:45 AM</u>

FACILITY: Phillips 66 Richmond Terminal

PERSON TO CONTACT FOR ADDITIONAL INFORMATION

Michael Morrison Phone number (510) 412-7606

PROVIDE ANY ADDITIONAL INFORMATION THAT WAS NOT INCLUDED IN THE 72-HOUR REPORT WHEN THE 72-HOUR REPORT WAS SUBMITTED, INCLUDING MATERIAL RELEASED AND ESTIMATED OR KNOWN QUANTITIES, COMMUNITY IMPACT, INJURIES, ETC.:

Ethanol was detected in two out of thirty-nine on-site wells (see attached site plan); Phillips 66 Remediation Department (RM) is working with the Regional Water Quality Control Board (RWQCB) to develop a course of action to address the impacts.

Phillips 66 is in the process of reviewing all contractor's bid proposals, and a contractor will be selected to make the repairs of the damaged section of the line.

30-DAY REPORT, PAGE 2 INCIDENT DATE: 3/23/2023

FACILITY: Phillips 66 Richmond Terminal

## I. INCIDENT INVESTIGATION RESULTS

Is the investigation of the incident complete at this time? Yes X No If the answer is no, when do you expect completion of the Investigation?

As soon as a permanent repair option is approved, and removal of the failed section is sent to a lab for analysis.

If the answer is yes, complete the following:

SUMMARIZE INVESTIGATION RESULTS BELOW OR ATTACH COPY OF REPORT:

SUMMARIZE PREVENTATIVE MEASURES TO BE TAKEN TO PREVENT RECURRENCE INCLUDING MILESTONE AND COMPLETION DATES FOR IMPLEMENTATION:

STATE AND DESCRIBE THE ROOT-CAUSE(S) OF THE INCIDENT: