

WILLIAM B. WALKER, M.D.  
HEALTH SERVICES DIRECTOR

RANDALL L. SAWYER  
CHIEF ENVIRONMENTAL HEALTH AND  
HAZARDOUS MATERIALS OFFICER

CONTRA COSTA  
HEALTH SERVICES  
HAZARDOUS MATERIALS PROGRAMS

4585 Pacheco Boulevard, Suite 100  
Martinez, California  
94553-2233  
Phone (925) 335-3200  
Fax (925) 646-2073

**ENTERED**

CONTRA COSTA  
HEALTH SERVICES

**COMPLAINT, INCIDENT, AND NOTIFICATION REPORT FORM**

Type (Circle One):  C  I  N

Received Date: 12/11/17 Received Time: 08:58 Received By: DL Lead: DL

Incident Date: Unknown Incident Time: unknown Assigned to: \_\_\_\_\_ Assigned Date: \_\_\_\_\_

CASE NUMBER: 17-12-11 - 02

**COMPLAINANT / REPORTING PARTY:**

Name: Michele Mancuso  RP is from Facility  Anonymous

Organization: County Watershed Program - Public Works

Primary Phone Number: 925-313-2236 Secondary Phone Number: \_\_\_\_\_

Email: \_\_\_\_\_

Address: \_\_\_\_\_

City: \_\_\_\_\_ State: \_\_\_\_\_ Zip Code: \_\_\_\_\_

**FACILITY / LOCATION OF INCIDENT:**

Name: \_\_\_\_\_ CUPA Facility I.D.: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Address: 6059 San Pablo Dam Road Unit: \_\_\_\_\_

City: Richmond State: CA Zip Code: \_\_\_\_\_

Location Description: San Pablo Creek

**INITIAL INCIDENT DESCRIPTION:** Oil barrel in creek with dead fish

**INCIDENT TYPE / DESCRIPTION:**

Community Warning System Level (Circle Highest Level):  N/A  0  1  2  3

FACILITY	ISO / MCAR	TRANSPORTATION	MISCELLANEOUS
<input type="checkbox"/> Fire or Explosion	<input type="checkbox"/> Fatality (one or more)	<input type="checkbox"/> Tank Truck	<input checked="" type="checkbox"/> Storm Drain/Creek
<input type="checkbox"/> Spill or Release	<input type="checkbox"/> > 24 hrs. Hospital, 3 or more people	<input type="checkbox"/> Railroad	<input type="checkbox"/> Drug Lab
<input type="checkbox"/> Startup or Shutdown	<input type="checkbox"/> Flammable Vapor Cloud > 5,000 lbs.	<input type="checkbox"/> On Water	<input type="checkbox"/> Disposal/Abandonment
<input type="checkbox"/> Flaring		<input type="checkbox"/> Pipeline	<input type="checkbox"/> Odor Complaint
<input type="checkbox"/> Upset		<input type="checkbox"/> Fuel Tank	<input type="checkbox"/> Other:

Time Enroute to Scene: 09:22 Time Arrived On Scene: 09:52 Time Departed From Scene: 10:56

**REFERRED TO OTHER AGENCY:**

**DTSC STATE FUNDING (if applicable):** CLU/ERER Number: \_\_\_\_\_

**STORMWATER STATUS (if applicable):**  Actual Discharge  Potential Discharge



**AGENCIES ON SCENE OR NOTIFIED:**

<b>Agency Type</b>	<b>Agency</b>	<b>O/N</b>	<b>Contact Person</b>	<b>Phone Number</b>	<b>Case Number</b>
Fire Department					
Law Enforcement					
Air District					
State OES					

**REPORT:**

08:58 Michele Mancuso of Contra Costa Watershed Program (Public Works) contacted CCHSHMP about a complaint their office received regarding an oil barrel and dead fish in San Pablo Creek. The information was provided by Jonathan Price of EBMUD, but Ms. Mancuso's attempts to reach Mr. Price by phone were unsuccessful. The closest address to the location of the drum and dead fish is 6059 San Pablo Dam Road. The nearest cross street is Castro Ranch Road.

09:01 HMS Lewis attempted to contact Mr. Price, but was unsuccessful. There was no CalOES spill notification. A page was sent out to dispatch Incident Response Team (IRT) to the location.

09:22 HMSs Asuncion and Pham departed office in HM4.

09:52 HMSs Asuncion and Pham are at 6059 San Pablo Dam Road. It is determined that access through a residential property is needed to observe the barrel. Mr. Robert Wyche, the resident that contacted EBMUD regarding the barrel and dead fish, gave CCHSHMP access to San Pablo Creek through his residential property. According to Mr. Wyche:

- There were no sanitary district discharges;
- Mr. Wyche removed about 15 - 20 dead fish;
- The barrel has been in the creek for about a month;
- The dead fish were not observed until about a week prior to the IRT being at the location; and
- There was a release from the San Pablo Dam.

The IRT observed 1 dead fish under water and a hole at the top edge of the drum. A film was observed on the water, but appeared to be biological, not chemical. Mr. Wyche said water had been released from the dam. The IRT is unable to remove the submerged drum. Based on observations and reported time that the drum has been in the water, it is not likely that the drum is discharging previous contents. The IRT will contact County Public Works to have the drum removed.

10:56 IRT departed location.

11:06 IRT arrived back at office in HM4.

**Additional Required Items: Bill of Lading, Request for Invoice, and Site Safety Plan**

Report Prepared by: DL