

Audit Summary

Sunset Packing & Cooling

Brentwood, California

Accident History:

The facility has not had an incident related to the regulated CalARP materials in the last five years.

Introduction


Contra Costa Health Services Hazardous Materials Programs (CCHSHMP) conducted a comprehensive audit/inspection of the policies and procedures developed by Sunset Packing & Cooling (Sunset) located at 830 Sunset Road, Brentwood. This audit, conducted in the summer of 2021, was performed to assess compliance with the California Accidental Release Prevention (CalARP) Program. The CalARP program requires the development of prevention programs such as maintenance, operating procedures, contractor safety, personnel training, incident investigations, and understanding hazards at the plant. The inspection also examines the management systems to implement these programs and the plant's emergency response program to make sure that the plant is prepared to respond to an emergency involving a hazardous chemical.

During a comprehensive CalARP audit for a facility like Sunset, CCHSHMP reviews individual safety programs by answering up to 110 questions. The CCHSHMP 2021 CalARP audit at Sunset resulted in 8 corrective actions for Sunset to implement and roughly 1 other items that are not required but may assist in accident prevention.

Based on our audit/inspection, some prevention programs need improvement to meet the regulatory requirements. Identified below are some notable issues found, both good and bad.

Notable Items:

- **Emergency Response:** CCHSHMP found that while the facility has an emergency response program, they need to ensure that drills involving local responders are completed and that the contact information for CCHSHMP is updated.
- **Maintenance:** CCHSHMP found that while the facility was conducting inspections to assure the mechanical integrity of the system, action items from these reviews were not completed and past due.
- **Hazard Review:** The facility completed a revalidation study to ensure that the ammonia refrigeration systems have all the necessary safeguards in place. However, improvement is needed in documenting the resolutions implemented. CCHSHMP found that some recommendations have not been completed and were past their due date.



Additional Information

To review the complete safety audit report, visit the Brentwood Library at 104 Oak Street, Brentwood, CA 94513 or call 925-655-3200 for an appointment to view the report at CCHMP's offices

For more information, questions, or comments regarding this facility or audit, please send an email to ARPTeam@hsd.cccounty.us

