



ENTERED

COMPLAINT, INCIDENT, AND NOTIFICATION REPORT FORM

Type (Circle One): C I N

Received Date: 06/11/18 Received Time: 14:05 Received By: HW Lead: TAJ

Incident Date: 06/11/18 Incident Time: _____ Assigned to: _____ Assigned Date: _____

CASE NUMBER: **180611 -04**

COMPLAINANT / REPORTING PARTY:

Name: Sheriff's Dispatch RP is from Facility Anonymous

Organization: _____

Primary Phone Number: (925) 646-2441 Secondary Phone Number: _____

Email: _____

Address: _____

City: _____ State: _____ Zip Code: _____

FACILITY / LOCATION OF INCIDENT:

Name: _____ CUPA Facility I.D.: _____

Phone Number: _____

Address: 632 Miner Rd. Unit: _____

City: Orinda State: CA Zip Code: 94563

Location Description: _____

INITIAL INCIDENT DESCRIPTION:

Punctured water tank from overturned cement truck is releasing water along with automotive fluids down the street and threatening a storm drain.

INCIDENT TYPE / DESCRIPTION:

Community Warning System Level (Circle Highest Level): N/A 0 1 2 3

FACILITY	ISO / MCAR	TRANSPORTATION	MISCELLANEOUS
<input type="checkbox"/> Fire or Explosion	<input type="checkbox"/> Fatality (one or more)	<input type="checkbox"/> Tank Truck	<input type="checkbox"/> Storm Drain/Creek
<input type="checkbox"/> Spill or Release	<input type="checkbox"/> > 24 hrs. Hospital, 3 or more people	<input type="checkbox"/> Railroad	<input type="checkbox"/> Drug Lab
<input type="checkbox"/> Startup or Shutdown	<input type="checkbox"/> Flammable Vapor Cloud > 5,000 lbs.	<input type="checkbox"/> On Water	<input type="checkbox"/> Disposal/Abandonment
<input type="checkbox"/> Flaring		<input type="checkbox"/> Pipeline	<input type="checkbox"/> Odor Complaint
<input type="checkbox"/> Upset		<input type="checkbox"/> Fuel Tank	<input type="checkbox"/> Other:

Time Enroute to Scene: 14:25 Time Arrived On Scene: 14:43 Time Departed From Scene: 16:12

REFERRED TO OTHER AGENCY:



DTSC STATE FUNDING (if applicable): CLU/ERER Number:	STORMWATER STATUS (if applicable): <input type="checkbox"/> Actual Discharge <input type="checkbox"/> Potential Discharge
--	---

AGENCIES ON SCENE OR NOTIFIED:

<u>Agency Type</u>	<u>Agency</u>	<u>O/N</u>	<u>Contact Person</u>	<u>Phone Number</u>	<u>Case Number</u>
Fire Department	Moraga-Orinda Fire District	O			
Law Enforcement	Orinda Police	O	Ofc. David Sandy		18-7459
Air District					
State OES		N			18-3804
	Berry Bros. Tow Co.	O			

REPORT:

6/12/2018: See attached narrative.

Additional Required Items: Bill of Lading, Request for Invoice, and Site Safety Plan

Trisha A. Johnson 6/12/2018

Report Prepared by: _____

WILLIAM B. WALKER, M.D.
HEALTH SERVICES DIRECTOR

RANDALL L. SAWYER
CHIEF ENVIRONMENTAL HEALTH AND
HAZARDOUS MATERIALS OFFICER



HAZARDOUS MATERIALS PROGRAMS

4585 Pacheco Boulevard
Martinez, California
94553-2233
Ph (925) 335-3200
Fax (925) 646-2073

INCIDENT REPORT
June 13, 2018

INCIDENT NO. 180611-04

INCIDENT DATE: June 11, 2018

LOCATION: 632 Miner Rd.
Orinda, CA 94563

RESPONDING

TEAM MEMBER(S): Trisha A. Johnson (lead), Devra Lewis, Amanda Ackerman, Adam Springer, and Ellen Dempsey

SUMMARY:

CCHSHMP received a call from Contra Costa County Sheriff's Dispatch at approximately 14:05 regarding an overturned cement truck releasing diesel onto a residential street and potentially reaching a nearby storm drain. At the time of the call, Moraga-Orinda Fire District was en route to the scene, while Orinda Police Department had several officers already on scene to isolate and deny entry to the incident. Specialists Amanda Ackerman, Ellen Dempsey, and Adam Springer were dispatched directly to the scene. Devra Lewis and I, Trisha Johnson, grabbed PPE and equipment in HM3/6868 and proceeded to the incident location. The incident location was on a hilly, narrow, and circuitous residential road; the cement truck overturned as it traveled on a slight decline on the road.

As team members approached the scene, several officers from the Orinda Police Department had controlled traffic access to the incident. By the time the responding team members arrived on scene (14:24-14:43), Engine 43 of the Moraga-Orinda had prevented the flow of the release into a nearby storm drain by using dirt from the side of the road and applying absorbent pads and booms. It appeared that most of the release consisted of water (due to the punctured water tank) and some automotive fluids, consisting of diesel fuel (fuel filter fell out and broke), antifreeze, motor oil, and diesel exhaust fluid (DEF). The release was still ongoing, but involved mostly water. The Haz Mat team applied absorbent pads upstream, closer to the cement truck, to help with the absorption of diesel and motor oil. The Berry Bros. Tow Company was on scene to upright the cement truck. I made a release report to the CalOES State Warning Center at 15:10. A copy of the CalOES report is attached.

The Haz Mat team discussed with the responsible party, Antioch Building Materials, about a clean-up plan for the materials used to stop the release from entering the storm drain. Both parties agreed that the team would remove contaminated dirt as hazardous waste and Antioch Building Materials would be pick up the rest of the non-hazardous waste contaminated dirt and sweep up the road. The Haz Mat team removed a ¾ -full 55-gallon drum of diesel-contaminated debris. The Haz Mat team departed from the scene at 16:12.

Specialist Adam Springer returned to the scene on the next morning, June 12, and reported that the responsible party cleaned up as agreed.



ATTACHMENT(S)

Incident Report Form #180611-04

CalOES Control Report #18-3804

CCHSHMP Bill of Lading

Invoice Request Form

REPORT

PREPARED BY:



Trisha A. Johnson, Hazardous Materials Specialist II

Contra Costa Health Services Hazardous Materials Programs (CCHSHMP)



Hazardous Materials Spill Report: Cal OES Control #:18-3804
Warning Center to: trisha.asuncion

06/11/2018 03:22 PM

Governor's Office of Emergency Services
Hazardous Materials Spill Report

DATE: 06/11/2018 | RECEIVED BY Cal OES: Justin Chistiansen | Cal OES
CNTRL #:18-3804
TIME: 1510 | RECEIVED BY OSPR: | NRC#:

1.a. PERSON NOTIFYING Cal OES

1. NAME: Trisha Johson | 2. AGENCY: Contra Costa County Haz
Mat
3. PHONE #: 925-335-3200 | 4. EXT: | 5. PAGER #:

1.b. PERSON REPORTING SPILL (If different from above):

1. NAME: | 2. AGENCY:
3. PHONE #: | 4. EXT: | 5. PAGER #:

2. SUBSTANCE TYPE:

a. SUBSTANCE: / b.QTY: / Amount / Measure / c. TYPE / d. OTHER / e.
PIPELINE / f. Vessel Over => 300 tons

1. Diesel Fuel , Motor oil , water, Anti freeze, DES- Diesel exhaust
fluid / = / unknown / N/A / PETROLEUM / / No / No

2.

3.

g. DESCRIPTION: Per caller report , an overturned cement truck had
water tank punctured causing a release of material onto cement.

h. CONTAINED: Not stopped | i. WATER INVOLVED: No

j. WATERWAY: | k. DRINKING WATER IMPACTED: No

l. KNOWN IMPACT: None

3.a. INCIDENT LOCATION: 632 Miner Road

b. CITY: Orinda | c. COUNTY: Contra Costa County | d. ZIP:

4. INCIDENT DESCRIPTION:

a. DATE: 6/11/2018 | b. TIME(Military): 1400 | c. SITE: Road |
d. CAUSE: Human Error

e. INJURIES: No | f. FATALITY: No | g. EVACUATIONS: No | h.
CLEANUP BY: Co. HazMat

e. INJURIES #: | f. FATALS #: | g. EVACS #:

5. SUSPECTED RESPONSIBLE PARTY:

a. NAME: Unknown | b. AGENCY: Antioch Building Materials

c. PHONE#: | d. EXT:

e. MAIL ADDRESS: Unknown

f. CITY: | g. STATE: CA | h. ZIP:

6. NOTIFICATION INFORMATION:

a. ON SCENE: Fire Dept., Police Dept. | b. OTHER ON SCENE:

- c. OTHER NOTIFIED:
- d. ADMIN. AGENCY: Contra Costa County Health Services Department
- e. SEC. AGENCY:
- f. ADDITIONAL COUNTY:
- g. ADMIN. AGENCY:
- h. NOTIFICATION LIST: DOG Unit: | RWQCB Unit: 2

AA/CUPA, DTSC, RWQCB, US EPA, USFWS

CONFIDENTIAL REMARKS:

Created by Warning Center on 6/11/2018 3:10:58 PM Last
Modified by Warning Center on 6/11/2018 3:21:39 PM

California State Warning Center
Governor's Office Emergency Services
Phone: (916) 845-8911
Warning.Center@oes.ca.gov

Link to Spill Report:

https://urldefense.proofpoint.com/v2/url?u=http-3A_w3.calema.ca.gov_operation_al_malhaz.nsf_SpillAllDocs_2DB04F3E6746FB85882582A90079DADF-3FOpenDocument&d=DwIBAg&c=RpR9LiQNioGO8A8CMgA1NQ&r=kFMDGVBGp7rtZe6oipiDT2WugZzQs2CBKtoHDIcj-p4&m=So80jHky7SgkYU5X-DHeN3BlnrvwRe2rYYw0RBvbmHw&s=LHuhVGEWiaXxJloPJMhNAErvG_100U5CE71pvPolTbk&e=