

CONTRA COSTA
 HEALTH SERVICES

CONTRA COSTA
 HAZARDOUS
 MATERIALS PROGRAMS

4585 Pacheco Boulevard, Suite 100
 Martinez, California 94553

Ph (925) 335-3200
 Fax (925) 646-2073
 ccchazmat@hsd.cccounty.us
 www.cchealth.org/hazmat/

COMPLAINT, INCIDENT, AND NOTIFICATION REPORT FORM

Type (Circle One): C I N

CASE NUMBER: 190524 - 01

Received Date: 05/24/19 Received Time: 9:40 AM Received By: AM Lead: IW

Incident Date: 5/24/19 Incident Time: Assigned to: Assigned Date:

COMPLAINANT / REPORTING PARTY:

Name: NATE RP is from Facility Anonymous

Organization: SRVFPD

Primary Phone Number: Secondary Phone Number:

Email:

Address:

City: State: Zip Code:

FACILITY / LOCATION OF INCIDENT:

Name: CUPA Facility I.D.:

Phone Number:

Address: 78 ROYAL RIDGE CT Unit:

City: ALAMO State: CA Zip Code: 94507

Location Description: C/S ROYAL OAKS DR

INITIAL INCIDENT DESCRIPTION:

SMALL PICK UP TRUCK WITH POOL CHEMICALS CAUGHT FIRE, SAN RAMON VALLEY FIRE ASKING FOR ASSISTANCE

INCIDENT TYPE / DESCRIPTION:

Community Warning System Level (Circle Highest Level): N/A 0 1 2 3

FACILITY	ISO / MCAR	TRANSPORTATION	MISCELLANEOUS
<input type="checkbox"/> Fire or Explosion <input type="checkbox"/> Spill or Release <input type="checkbox"/> Startup or Shutdown <input type="checkbox"/> Flaring <input type="checkbox"/> Upset	<input type="checkbox"/> Fatality (one or more) <input type="checkbox"/> > 24 hrs. Hospital, 3 or more people <input type="checkbox"/> Flammable Vapor Cloud > 5,000 lbs.	<input type="checkbox"/> Tank Truck <input type="checkbox"/> Railroad <input type="checkbox"/> On Water <input type="checkbox"/> Pipeline <input type="checkbox"/> Fuel Tank	<input checked="" type="checkbox"/> Storm Drain/Creek <input type="checkbox"/> Drug Lab <input type="checkbox"/> Disposal/Abandonment <input type="checkbox"/> Odor Complaint <input type="checkbox"/> Other:

Time Enroute to Scene: 10:03 AM Time Arrived On Scene: 10:22 AM Time Departed From Scene: 2:48 PM

REFERRED TO OTHER AGENCY:



DTSC STATE FUNDING (if applicable): CLU/ERER Number:	STORMWATER STATUS (if applicable): <input checked="" type="checkbox"/> Actual Discharge <input type="checkbox"/> Potential Discharge
--	--

AGENCIES ON SCENE OR NOTIFIED:

<u>Agency Type</u>	<u>Agency</u>	<u>O/N</u>	<u>Contact Person</u>	<u>Phone Number</u>	<u>Case Number</u>
Fire Department	San Ramon Vally FD	O	Bruno Spani		
Law Enforcement					
Air District					
State OES	CA Fish & Wildlife	O	H. Twomney		

REPORT:

At 9:40 AM on May 24, 2019, Contra Costa Health Services Hazardous Materials Programs (CCHSHMP) received a request for assistance from San Ramon Valley Fire Protection District (SRVFPD) related to a pick up truck carrying pool chemicals that had caught fire.

Hazardous Materials Specialists (HMS) Bryant, Umemoto, Duncan, and Dwight responded to the scene in HM1 and HM3, departing at 10:03 AM and arriving on scene at 10:22 AM. The fire had been extinguished when CCHSHMP arrived on scene. SRVFPD BC Bruno Spani reported that some fire suppression water had entered the storm drain, but it had a neutral pH and air monitoring around the storm drain did not indicate any concentrations above background levels.

Representatives from the pool truck company, AquaPro, stated that the truck was carrying approximately 25 1-gallon containers of sodium hypochlorite, 3 1-gallon containers of muriatic (hydrochloric) acid, granular chlorine (sodium dichlor), chlorine tablets (dichlorotrazetrine) sodium bicarbonate, and some small quantities of miscellaneous chemicals including copper algicide.

CCHSHMP and SRVFPD personnel (Laugero and Shafer) conducted four joint entries to remove the hazardous materials from the pick up truck and segregate and containerize them for proper disposal. Some containers could be removed intact, but the fire had caused many of the containers to melt and fuse together. Liquid was pumped out of the compromised containers and absorbant pads were used to collect the remainder of the liquid. Air monitoring was conducted in the exclusion and support zones using a multigas meter and chlorine gas badges.

HMS Pham and LeCount arrived on scene in privately owned vehicles at 1:00 PM, and HMS Williams in HM4 at 1:30 PM, to further assist with response operations. Once the hazardous materials were removed from the truck and segregated into appropriate containers for disposal by CCHSHMP as hazardous waste, CCHSMP applied a neutralizing spray to the truck bed. After confirming the pH was neutral, the pick up truck was released to the tow truck company for removal from the scene.

CCHSHMP transported the hazardous waste generated from clean up activities under bill of lading to the CCHSHMP hazardous waste storage area pending proper disposal. HM1, HM3, and HM4 departed the scene at 2:48 PM and arrived at the CCHSHMP truck bay at 3:28 PM.

The release is documented in OES Report #19-3352. H. Twomney of California Fish & Wildlife Services responded to the scene to evaluate potential effects to waterways.

Additional Required Items: Bill of Lading, Request for Invoice, and Site Safety Plan

Report Prepared by: S. Dwight

[EXTERNAL] Hazardous Materials Spill Report: Cal OES Control #:19-3352

Warning Center <Warning.Center@oes.ca.gov>

Fri 2019-05-24 11:02 AM

To:ccchazmat@hsd.cccounty.us <ccchazmat@hsd.cccounty.us>;

PLEASE CONFIRM RECEIPT VIA EMAIL OR PHONE 916-845-8911

Governor's Office of Emergency Services
Hazardous Materials Spill Report

DATE: 05/24/2019 | RECEIVED BY Cal OES: Devin Clarke | Cal OES CNTRL #:19-3352

TIME: 1049 | RECEIVED BY OSPR: | NRC#:

1.a. PERSON NOTIFYING Cal OES

1. NAME: Steve Laugero | 2. AGENCY: San Ramon Valley Fire
3. PHONE #: 209-872-4831 | 4. EXT: | 5. PAGER #:

1.b. PERSON REPORTING SPILL (If different from above):

1. NAME: | 2. AGENCY:
3. PHONE #: | 4. EXT: | 5. PAGER #:

2. SUBSTANCE TYPE:

a. SUBSTANCE: / b.QTY: / Amount / Measure / c. TYPE / d. OTHER / e. PIPELINE / f. Vessel Over => 300 tons

1. Liquid Chlorine / = / 25 / Gal(s) / CHEMICAL / / No / No

2. Muriatic Acid / = / 3 / Gal(s) / CHEMICAL / / No / No

3. Soda Ash Powder / = / 50 / Lbs. / CHEMICAL / / No / No

g. DESCRIPTION: Per the caller a pool supply truck had an engine fire that spread to the bed of the truck due to unknown causes. Per the caller the truck had 25 gallons of liquid chlorine, 3 gallons of muriatic acid and 50 lbs of soda ash powder being transported in the bed. Per the caller as a result of the fire and fire suppression efforts a mixture of the chemicals

did enter the storm drain. Per the caller total amount of the chemicals into the storm drain is unknown. Per the caller the driver did sustain minor burn injuries and denied transport to the hospital. County Hazmat is on scene to assist with clean up.

- h. CONTAINED: Stopped | i. WATER INVOLVED: Yes
- j. WATERWAY: Storm Drain | k. DRINKING WATER IMPACTED: Unknown
- l. KNOWN IMPACT: Unknown

- 3.a. INCIDENT LOCATION: 78 Royal Ridge Court
- b. CITY: Alamo | c. COUNTY: Contra Costa County | d. ZIP:

- 4. INCIDENT DESCRIPTION:
- a. DATE: 5/24/2019 | b. TIME(Military): 0914 | c. SITE: Road |
- d. CAUSE: Other Reason for Other: Fire
- e. INJURIES: Yes | f. FATALITY: No | g. EVACUATIONS: No | h.
- CLEANUP BY: Hazmat. Hazmat
- e. INJURIES #: 1 | f. FATALS #: | g. EVACS #:

- 5. SUSPECTED RESPONSIBLE PARTY:
- a. NAME: | b. AGENCY: Aqua Pro Pool and Chemical Service
- c. PHONE#: 925-482-4099 | d. EXT:
- e. MAIL ADDRESS:
- f. CITY: | g. STATE: CA | h. ZIP:

- 6. NOTIFICATION INFORMATION:
- a. ON SCENE: Fire Dept. | b. OTHER ON SCENE: Co Hazmat
- c. OTHER NOTIFIED:
- d. ADMIN. AGENCY: Contra Costa County Health Services Department
- e. SEC. AGENCY:
- f. ADDITIONAL COUNTY: | g. ADMIN. AGENCY:
- h. NOTIFICATION LIST: DOG Unit: | RWQCB Unit: 2

AA/CUPA, DTSC, RWQCB, US EPA, USFWS, DFG-OSPR, DWP-DO, DPR, LANDS, PARKS & REC, Co/WP, Co/Hlth, Co/E-Hlth

CONFIDENTIAL REMARKS:

Created by Warning Center on 5/24/2019 10:49:29 AM Last
Modified by Warning Center on 5/24/2019 11:01:43 AM

California State Warning Center
Governor's Office Emergency Services
Phone: (916) 845-8911
Warning.Center@oes.ca.gov

Link to Spill Report:

https://urldefense.proofpoint.com/v2/url?u=http-3A_w3.calema.ca.gov_operational_malhaz.nsf_SpillAllDocs_6DD0D789656FD20A882584040061EA12-3FOpenDocument&d=DwIBAg&c=RpR9LiQNIoGO8A8CMgA1NQ&r=S0jS0A081QNgB4a-k_X9SD1TTubB3u_sfrG7WkczC2Lg&m=S-ZSKHvcVZjbopOvL8DaxwhzEaacYXt1DVL0uFXmZIU&s=XqtXbDu_SECPCZ7f1mRgs_H_PELH-RchKcB-T9wtPqA&e=