WILLIAM B. WALKER, M.D. HEALTH SERVICES DIRECTOR


RANDALL L. SAWYER CHIEF ENVIRONMENTAL HEALTH AND HAZARDOUS MATERIALS OFFICER



Contra Costa Health Services

HAZARDOUS MATERIALS PROGRAMS

4585 Pacheco Boulevard, Suite 100 Martinez, California 94553-2233 Phone (925) 335-3200 Fax (925) 646-2073



COMPLAINT, INCIDENT, AND NOTIFICATION REPORT FORM

	······································							
Type (Circle One): C I N		CASE NUI	MBER: 17070 5 -01					
Received Date: 07/05/17	Received Time: 11:34	Received By: TA	Lead: TA					
Incident Date: 07/05/17	Incident Time:	Assigned to:	Assigned Date:					
COMPLAINANT / REPORTING PARTY:								
Name: Stephen Pree, Envir	ronmental Programs Manag	er ☐ RP is	s from Facility					
	rito Public Works Departme	ent						
Primary Phone Number: (510) 867-9665 Secondary Phone Number:								
Email:								
Address:								
City:		State: 2	State: Zip Code:					
FACILITY / LOCATION OF IN	ICIDENT:							
Name: Cerrito Creek		CUPA I	CUPA Facility I.D.:					
Phone Number:								
Address:		Unit:						
City: El Cerrito		State: CA z	State: CA Zip Code: 94530					
Location Description: Creek								
INITIAL INCIDENT DESCRIPTION: Release of white substance in Cerrito Creek, El Cerrito								
Community Warning System Level (Circle Highest Level): N/A 0 1 2 3								
	nity warning System Level (C							
FACILITY	ISO / MCAR	TRANSPORTATIO						
	☐ Fatality (one or more)	□ Tank Truck	Storm Drain/Creek Storm Drain/Creek					
	□ > 24 hrs. Hospital, 3 or	□ Railroad	□ Drug Lab					
□ Startup or Shutdown	more people	□ On Water □ Pipeline	☐ Disposal/Abandonment					
□ Flaring □ Upset	□ Flammable Vapor Cloud > 5,000 lbs.	□ Fipeline □ Fuel Tank	□ Odor Complaint □ Other:					
		1						
Time Enroute to Scene: 12:00 Time Arrived On Scene: Time Departed From Scene: 13:16								
REFERRED TO OTHER AGENCY:								
			•					
		TORMWATER STATUS (if applicable):						
CLU/FRFR Number:		□ Actual Discharge □ Potential Discharge						



AGENCIES ON SCENE OR NOTIFIED:

Agency Type	<u>Agency</u>	O/N	Contact Person	Phone Number	Case Number
Fire Department					
Law Enforcement					
Air District				(1)	
State OES					1
				·	The second secon

REPORT:

7/5/17: Received a call from CeCe Sellgren of CCC Clean Water Program. She received a call from Stephen Pree of the City of El Cerrito regarding a release of a white substance (possibly paint?) into the area of Cerrito Creek adjacent to the El Cerrito Plaza. I contacted Mr. Pree. He requested that the Haz Mat Team help with the clean-up of the impacted area of the creek. The City of El Cerrito had laid down a coffer dam to reduce further impact of the creek downstream.

A. Ackerman was already out in the field and was dispatched directly to the incident location. She arrived at 12:16 pm and made contact with Mr. Pree.

A. Springer and S. Heller departed from the office in HM1/6824 to the incident location and arrived on scene at approximately 12:44 pm. A tailgate meeting was conducted prior to any mitigation actions by CCHSHMP to discuss safety and tactical considerations. Springer and Heller assessed a sample of the white substance in the creek to be pH neutral and not an oxidizer. Dissolved oxygen was 7.8-8.1 upstream, mid-stream, and downstream of the contained release. Also, wildlife (e.g., insects, fish) in the creek appear to be unaffected by the release. The white substance may be a combination of water-based paint (possibly latex) and joint compound.

CCHSHMP tried to remove the material; but it appeared that the material had dried up, making it difficult to be removed/separated from the creek substrate of sand and gravel. CCHSHMP departed from scene at 13:16 pm.

Additional Required Items: Bill of Lading, Request for Invoice, and Site Safety Plan

Report Prepared by:

Trisha Asuncion 7/5/17